

Fireware XTM v11.6.7 Release Notes

Supported XTM 21, 22, and 23
Devices XTM 21-W, 22-W, and 23-W

Fireware XTM OS Build 433199

WatchGuard N/A System WatchGuard recommends you use WSM v11.8 to manager Build manage Fireware XTM OS v11.6.7.

Revision Date 24 October 2013

Introduction

Fireware XTM v11.6.7 is a maintenance release for XTM 21, XTM 22, and XTM 23 wired and wirelss devices.

This release provides several bug fixes and stability improvements for our XTM 2 Series customers, including improvements to spamBlocker. Leveraging technology from Commtouch, spamBlocker now offers higher efficacy and reduced false positives measured in testing, as well as an updated UI for Bulk mail handling, Virus Outbreak Detection, and Proactive Patterns.

There is no new WatchGuard System Manager release for Fireware XTM v11.6.7. We recommend that you use WatchGuard System Manager v11.8 to manage XTM devices that run v11.6.7.

See the Resolved Issues section below for a complete list of resolved issues.

Before You Begin

Before you install this release, make sure that you have:

- A WatchGuard XTM 21, 22, or 23 device, wired or wireless.
- The required hardware and software components as shown below. If you use WatchGuard System
 Manager (WSM), make sure your WSM version is equal to or higher than the version of Fireware XTM
 OS installed on your XTM device and the version of WSM installed on your Management Server.
- Feature key for your XTM device If you upgrade your XTM device from an earlier version of Fireware XTM OS, you can use your existing feature key.

If you have a new XTM physical device, make sure you use the instructions in the XTM Quick Start Guide that shipped with your device.

Product documentation for all WatchGuard products is available on the WatchGuard web site at www.watchguard.com/help/documentation.

Localization

This release includes localized management user interfaces (WSM application suite and Web UI) and product help.

Content related to new features may not be localized in this release. Supported languages are:

- Chinese (Simplified, PRC)
- French (France)
- Japanese
- Spanish (Latin American)

In addition to these languages, we offer localized Web UI support for Korean and Traditional Chinese. Only the Web UI itself has been localized. WSM, and all help files and user documentation, remain in English for these two languages.

Note that most data input must still be made using standard ASCII characters. You can use non-ASCII characters in some areas of the UI, including:

- · Proxy deny message
- · Wireless hotspot title, terms and conditions, and message
- · WatchGuard Server Center users, groups, and role names

Any data returned from the device operating system (e.g. log data) is displayed in English only. Additionally, all items in the Web UI System Status menu and any software components provided by third-party companies remain in English.

Fireware XTM Web UI

The Web UI will launch in the language you have set in your web browser by default. The name of the currently selected language is shown at the top of each page. To change to a different language, click the language name that appears. A drop-down list of languages appears and you can select the language you want to use.

WatchGuard System Manager

When you install WSM, you can choose what language packs you want to install. The language displayed in WSM will match the language you select in your Microsoft Windows environment. For example, if you use Windows 7 and want to use WSM in Japanese, go to Control Panel > Regions and Languages and select Japanese on the Keyboards and Languages tab as your Display Language.

WebCenter, Quarantine Web UI, and Wireless Hotspot

These web pages automatically display in whatever language preference you have set in your web browser.

Fireware XTM v11.6.x and WSM v11.8 Operating System Compatibility

Revised April 2013

WSM/ Fireware XTM Component	Microsoft Windows XP SP2 (32-bit) & Vista (32 &64-bit)	Microsoft Windows 7 and 8 (32-bit & 64-bit)	Microsoft Windows Server 2003 SP2 (32-bit)	Microsoft Windows Server 2008 & 2008 R2	Microsoft Windows Server 2012 (64- bit)	Mac OS X v10.5, v10.6, & v10.7, v10.8	Mobile Devices: Android 4.x and higher, iOS
WatchGuard System Manager Application	✓	✓	✓	✓	✓		
Fireware XTM Web UI Supported Browsers: IE 7, 8, and 9, Firefox 3.x & above	✓	✓	✓	✓	✓	✓	
WebCenter Web UI Supported browsers: Firefox 3.5 & above, IE8 & above, Safari 5.0 & above, Chrome 10 & above. Javascript required.	✓	✓	✓	✓	✓	✓	
WatchGuard Servers	\checkmark	\checkmark	\checkmark	\checkmark	\checkmark		
Single Sign-On Agent Software (Includes Event Log Monitor)			✓	✓	✓		
Single Sign-On Client Software	✓	✓	✓	✓			
Terminal Services Agent Software*			✓	✓	✓		
Mobile VPN with IPSec Client Software	✓	✓				√ **	√ **
Mobile VPN with SSL Client Software	✓	✓	✓			✓	

Notes about Microsoft Windows support:


- For Microsoft Windows Server 2008, we support both 32-bit and 64-bit support. For Windows Server 2008 R2, we support 64-bit only.
- Windows 8 support does not include Windows RT.


Browser compatibility:

- Fireware XTM Web UI is supported on IE 7, 8, and 9, and Firefox 3.x and above.
- WebCenter Web UI is supported on IE 8 and above, Firefox 3.5 and above, Safari 5.0 and above, and Chrome 10 and above. Javascript is required.

Authentication Support

This table gives you a quick view of the types of authentication servers supported by key features of Fireware XTM. Using an authentication server gives you the ability to configure user and group-based firewall and VPN policies in your XTM device configuration. With each type of third-party authentication server supported, you can specify a backup server IP address for failover.





	Active Directory ¹	LDAP	RADIUS 2	SecurID 2	Firebox (Firebox-DB) Local Authentication
Mobile VPN with IPSec/Shrew Soft	✓	✓	√ 3	-	✓
Mobile VPN with IPSec for iPhone/iPad iOS and Mac OS X		✓		✓	✓
Mobile VPN with IPSec for Android devices	✓	✓	✓	-	✓
Mobile VPN with SSL for Windows	\checkmark	\checkmark	√ 4	√ 4	\checkmark
Mobile VPN with SSL for Mac	\checkmark	\checkmark		\checkmark	\checkmark
Mobile VPN with PPTP	-	-	\checkmark	N/A	\checkmark
Built-in Authentication Web Page on Port 4100	✓	✓	✓	✓	✓
Windows Single Sign-On Support (with or without client software)	✓	-	-	-	-
Terminal Services Manual Authentication	✓				✓
Terminal Services Authentication with Single Sign-On	√ 5	-	-	-	-
Citrix Manual Authentication					✓

^{*} Terminal Services support with manual or Single Sign-On authentication operates in a Microsoft Terminal Services or Citrix XenApp 4.5, 5.0, 6.0 and 6.5 environment.

^{**} Native (Cisco) IPSec client is supported for Mac OS and iOS.

- 1. Active Directory support includes both single domain and multi-domain support, unless otherwise noted.
- 2. RADIUS and SecurID support includes support for both one-time passphrases and challenge/response authentication integrated with RADIUS. In many cases, SecurID can also be used with other RADIUS implementations, including Vasco.
- 3. The Shrew Soft client does not support two-factor authentication.
- 4. Fireware XTM supports RADIUS Filter ID 11 for group authentication.
- 5. Only single domain Active Directory configurations are supported. For information about the supported Operating System compatibility for the WatchGuard TO Agent and SSO Agent, see the current Fireware XTM and WSM Operating System Compatibility table.

Downloading Software

- 1. Log in to the WatchGuard Portal and select the Articles & Software tab.
- 2. From the Search section, clear the Articles and Known Issues check boxes and search for available Software Downloads. Select the XTM device for which you want to download software.

There are several software files available for download. See the descriptions below so you know what software packages you will need for your upgrade.

WatchGuard System Manager

All users can now download the WatchGuard System Manager software. There is no WatchGuard System Manager v11.6.7. We recommend that you use WatchGuard System Manager v11.8 to manage Fireware XTM v11.6.7.

Fireware XTM OS

Select the correct Fireware XTM OS image for your XTM device. Use the .exe file if you want to install or upgrade the OS using WSM. Use the .zip file if you want to install or upgrade the OS using the Fireware XTM Web UI. Use the .ova file to deploy a new XTMv device.

If you have	Select from these Fireware XTM OS packages
XTM 2 Series Models 21-23	<pre>XTM_OS_XTM2_11_6_7.exe xtm_xtm2_11_6_7.zip</pre>

Single Sign-On Software

There are two files available for download if you use Single Sign-On. The SSO Agent software has been updated for this release.

- WG-Authentication-Gateway_11_7_4.exe (SSO Agent software required for Single Sign-On and includes optional Event Log Monitor for clientless SSO)
- WG-Authentication-Client 11 7.msi (SSO Client software optional)

For information about how to install and set up Single Sign-On, see the product documentation.

Terminal Services Authentication Software

TO_AGENT_SETUP_11_7_4.exe (This installer includes both 32-bit and 64-bit file support)

Mobile VPN with SSL Client for Windows and Mac

There are two files available for download if you use Mobile VPN with SSL. These files have not been updated for this release.

- WG-MVPN-SSL_11_7_3.exe (Client software for Windows)
- WG-MVPN-SSL_11_7_3.dmg (Client software for Mac)

Mobile VPN with IPSec client for Windows

We now support the Shrew Soft VPN client for Windows v2.2, which you can download from our web site. Shrew Soft has recently released a v2.2.1 client, available on their web site, which introduces a new "Pro" version available at an extra cost with additional features. WatchGuard recommends you use the no-cost Standard version of the client as it includes all functionality supported in the v2.2 VPN client. If you want to use the v2.2.1 client, we recommend you read this Knowledge Base article first.

Upgrade from Fireware XTM v11.x to v11.6.7

Before you upgrade from Fireware XTM v11.x to Fireware XTM v11.6.7, download and save the Fireware XTM OS file that matches the WatchGuard device you want to upgrade. You can find all available software on the WatchGuard Portal, Articles & Software tab. You can use Policy Manager or the Web UI to complete the upgrade procedure. We strongly recommend that you back up your device configuration and your WatchGuard Management Server configuration before you upgrade. It is not possible to downgrade without these backup files.

If you use WatchGuard System Manager (WSM), make sure your WSM version is equal to or higher than the version of Fireware XTM OS installed on your XTM device and the version of WSM installed on your Management Server. There is no WatchGuard System Manager v11.6.7. We recommend that you use WatchGuard System Manager v11.8 to manage Fireware XTM v11.6.7.

If you are upgrading to WSM 11.7.3 from WSM v11.4.x or earlier, it is important to back up your Log and Report Server data using the procedure described in the Knowledge Base article Log and Report Server Changes in XTM v11.5.1. This is necessary because the Log and Report Server database structure changed in WSM v11.5.1. When you upgrade to WSM v11.5.1 or higher for the first time, the timestamps of existing log and report data will be converted to UTC from the local time zone. This Knowledge Base article gives you details on this upgrade, and important information about the Log and Report Manager (also new in WSM v11.5.1).

Back up your WatchGuard Management Server Configuration

From the computer where you installed the Management Server:

- From WatchGuard Server Center, select Backup/Restore Management Server.
 The WatchGuard Server Center Backup/Restore Wizard starts.
- Click Next.
 - The Select an action screen appears.
- 3. Select Back up settings.
- 4. Click Next.
 - The Specify a backup file screen appears.
- 5. Click **Browse** to select a location for the backup file. Make sure you save the configuration file to a location you can access later to restore the configuration.
- 6. Click Next.
 - The WatchGuard Server Center Backup/Restore Wizard is complete screen appears.
- 7. Click **Finish** to exit the wizard.

Upgrade to Fireware XTM v11.6.7 from Web UI

- Go to System > Backup Image or use the USB Backup feature to back up your current configuration file.
- 2. On your management computer, launch the OS software file you downloaded from the WatchGuard Software Downloads Center.
 - If you use the Windows-based installer, this installation extracts an upgrade file called [xtm series]_ [product code].sysa-dl I to the default location of C:\Program Files(x86)\Common files\WatchGuard\resources\FirewareXTM\11.6.7\[model] or [model][product_code].
- Connect to your XTM device with the Web UI and select System > Upgrade OS.
- 4. Browse to the location of the [xtm series] [product code].sysa-dl from Step 2 and click Upgrade.

Upgrade to Fireware XTM v11.6.7 from WSM/Policy Manager v11.8

- Select File > Backup or use the USB Backup feature to back up your current configuration file.
- On your management computer, launch the OS executable file you downloaded from the WatchGuard Portal. This installation extracts an upgrade file called [xtm series]_[product code].sysa-dl I to the default location of C:\Program Files(x86)\Common
 - files\WatchGuard\resources\FirewareXTM\11.6.7\[model] or [model][product_code].
- 3. Install and open WatchGuard System Manager v11.8. Connect to your XTM device and launch Policy Manager.
- 4. From Policy Manager, select **File > Upgrade**. When prompted, browse to and select the [xtm series]_ [product code].sysa-dl file from Step 2.

Downgrade Instructions

Downgrade from WSM v11.6.x to WSM v11.x

If you want to revert from v11.6.x to an earlier version of WSM, you must uninstall WSM v11.6.x. When you uninstall, choose **Yes** when the uninstaller asks if you want to delete server configuration and data files. After the server configuration and data files are deleted, you must restore the data and server configuration files you backed up before you upgraded to WSM v11.6.x.

Next, install the same version of WSM that you used before you upgraded to WSM v11.6.x. The installer should detect your existing server configuration and try to restart your servers from the **Finish** dialog box. If you use a WatchGuard Management Server, use WatchGuard Server Center to restore the backup Management Server configuration you created before you first upgraded to WSM v11.6.x. Verify that all WatchGuard servers are running.

Downgrade from Fireware XTM v11.6.x to Fireware XTM v11.x

There are some downgrade restrictions:

- You cannot downgrade an XTM 2050 or an XTM 330 to a version of Fireware XTM OS lower than v11.5.1.
- You cannot downgrade an XTM 5 Series model 515, 525, 535 or 545 to a version of Fireware XTM OS lower than v11.6.1.
- You cannot downgrade an XTM 2 Series model 25 or 26, or an XTM 33 to a version of Fireware XTM OS lower than v11.5.2.
- You cannot downgrade XTMv to a version of Fireware XTM OS lower than v11.5.4.

If you want to downgrade from Fireware XTM v11.6.x to an earlier version of Fireware XTM, you either:

- Restore the full backup image you created when you upgraded to Fireware XTM v11.6.x to complete the downgrade; or
- Use the USB backup file you created before the upgrade as your auto-restore image, and then boot into recovery mode with the USB drive plugged in to your device. This is not an option for XTMv users.

To start a WatchGuard XTM 330, 5 Series, 8 Series, XTM 1050, or XTM 2050 device in recovery mode:

- 1. Power off the XTM device.
- 2. Press the up arrow on the device front panel while you turn the power on.
- 3. Keep the button depressed until "Recovery Mode starting" appears on the LCD display.

To start a WatchGuard XTM 2 Series or XTM 33 device in recovery mode:

- 1. Disconnect the power.
- 2. Press and hold the Reset button on the back while you connect the power to the device.
- 3. Keep the button depressed until the Attn light on the front turns solid orange.

Resolved Issues

This release resolves a number of problems found in earlier Fireware XTM releases.

- You can now delete Mobile VPN policies from your configuration using the Web UI. [72198]
- An issue that caused Firebox System Manager > Status Report to include false data for unconfigured interfaces has been resolved. [74419]
- The authentication page on the XTM device that you use to download Mobile VPN with SSL client software no longer enables the browser toprompt you to save a username and password. [75116]
- This release resolves an issue that caused the Gateway AntiVirus scand process to fail on some devices after a signature update. [75869]
- A potential buffer overflow vulnerability has been addressed in this release. [76784]
- Modem failover to a model connected to the USB serial console now operates correctly. [71684]
- Multi-cast traffic sent via branch office VPN is no longer denied. [77066]
- Mobile VPN with IPSec traffic is no longer incorrectly routed through the wrong interface when you use multi-WAN enabled in round-robin mode. [77109]

Known Issues and Limitations

These are known issues for Fireware XTM v11.6.6 and all management applications. Where available, we include a way to work around the issue.

General

- The "Sysb" version displayed in the Firebox System Manager Status Report will show blank for XTM models 2,5,8, and 1050 that were manufactured prior to the XTM v11.5.1 release.
- ICMP flood protection works differently in 11.5.1 than in earlier versions. In v11.5.1 the XTM device
 counts the combined total number of ping requests and replies, rather than just the total number of ping
 requests. Since the default threshold for ICMP Flood Attack protection did not increase, the flood
 protection could trigger more frequently than it did in earlier releases. [63094]

Workaround

In the Default Packet Handling settings, increase the threshold for Drop ICMP Flood Attack from the default value of 1000 packets/second to a higher number.

- When the level of free memory on your XTM device is lower than 20M, saving your XTM device configuration to the device can cause network disruption. [64474]
- The ETH1 interface on the XTM 830F is a fiber-optic port, so you cannot use the WSM Quick Setup Wizard from a computer with an Ethernet interface. Use a computer with a Fiber NIC, or connect using a switch with both Fiber and Ethernet interfaces. [59742]

- On XTM 2 Series devices, the load average is always displayed at 1 or higher, even when there is no load on the device. [63898]
- An XTM 2 Series device can take up to 5 minutes to reboot.
- When you use the Policy Manager > File > Backup or Restore features, the process can take a long time but does complete successfully. [35450]
- You cannot downgrade an XTM 2 Series device from v11.5.1 to v11.4.1 with the Upgrade OS option in the Web UI. [63323]
- Fireware XTM does not support BGP connections through an IPSec VPN tunnel to Amazon Web Services. VPN tunnels that do not use BGP are supported. [41534]
- The XTM Configuration Report does not contain all settings. Settings not included are:
 - Secondary interface IP address [66990]
 - Configured QoS settings [66992]
 - Static MAC bindings [66993]
 - o IPv6 configuration [66994]

XTMv

XTMv does not automatically change the self-signed certificate when its serial number changes. [66668]

Workaround

A new self-signed certificate with the correct serial number is generated if you manually delete the certificate from Firebox System Manager > View > Certificates and then reboot the XTMv device.

If you import the OVA file in VMware Player (which is not officially supported in this release), you must
use the "Enter" key on your keyboard to accept the XTMv End User License Agreement (EULA). The
OK and Cancel buttons at the conclusion of the EULA do not appear in VMware Player.

WatchGuard System Manager

- If you use Firebox System Manager to ping across a VPN tunnel, you get a message that reads "No Buffer Space Available." This is not a memory problem. You see this message if the VPN tunnel is not established. Make sure the VPN tunnel is up and try again. [59339]
- WatchGuard System Manager does not display the correct IP address for the default gateway of an XTM device that has no External interface. [56385]
- When you install WatchGuard System Manager or any server software on a computer running Microsoft Windows XP, compatibility mode should not be enabled even if prompted by Windows, for any of the WSM applications, including the installer. [56355]
- Remote managed Firebox or XTM devices configured in Drop-in Mode may not be able to connect to a
 Management Server that is behind a gateway Firebox or XTM device also configured in Drop-in Mode.

 //330561
- If you restore a backup image to a managed client device managed by a Management Server, it is
 possible that the shared secret becomes out of sync.

Workaround

Connect to the Management Server from WSM. Select the managed device and select **Update Device**. Select the radio button **Reset server configuration (IP address/ Hostname, shared secret)**.

During a WSM upgrade, install, or uninstall on a 64-bit Windows systems, any running applications
detected by the WSM installer can be stopped successfully, but the installer may not recognize that
they have been stopped. [39078]

Workaround

Close the installer application. Right-click on the WatchGuard Server Center icon on your Windows task bar and exit the WatchGuard Server Center. Make sure all detected applications are stopped and then retry the WSM install or uninstall.

• When you run the WSM v11.3.x or higher installer (either the WSM client component only or any selected WSM server components) on Microsoft SBS (Small Business Server) 2008 and 2011 on a computer installed with a 64-bit operating system, you see a Microsoft Windows error "IssProc.x64 has stopped working". When you close the error dialog box, the installation completes. [57133]

Web UI

- The Fireware XTM Web UI does not support the configuration of some features. These features include:
 - FireCluster
 - Certificate export
 - You cannot turn on or off notification of BOVPN events
 - You cannot add or remove static ARP entries to the device ARP table
- You cannot change the order of policies with drag-and-drop from the Fireware XTM Web UI. You must use the **Move Up** and **Move Down** buttons. *[70587]*
- You cannot get the encrypted Mobile VPN with IPSec end-user configuration profile, known as the .wgx file. The Web UI generates only a plain-text version of the end-user configuration profile, with file extension .ini.
- You cannot edit the name of a policy, use a custom address in a policy, or use Host Name (DNS lookup) to add an IP address to a policy.
- If you configure a policy in the Web UI with a status of Disabled, then open Policy Manager and make a change to the same policy, the action assigned to the policy when it denies packets is changed to Send TCP RST. [34118]
- You cannot create read-only Mobile VPN with IPSec configuration files with the Web UI. [39176]

Command Line Interface (CLI)

- The CLI does not support the configuration of some features:
 - You cannot add or edit a proxy action.
 - You cannot get the encrypted Mobile VPN with IPSec end-user configuration profile, known as the .wgx file. The CLI generates only a plain-text version of the end-user configuration profile, with file extension .ini.
- The CLI performs minimal input validation for many commands.
- For the XTM 2050, the output of the CLI command "show interface" does not clearly indicate the interface number you use in the CLI to configure an interface. The "show interface" CLI command shows the interface number as the interface label on the front of the device (A0, A2 ... A7; B0, B1 ... B7; C0, C1) followed by a dash, and then the consecutive interface number (0 17), for all interfaces. [64147]

Workaround

Use the consecutive interface number that appears after the dash as the interface number to configure the interface. For the B1-9 interfaces, the interface number in the CLI command should be in the range 8-15. For the C0-1 interfaces, the interface number in the CLI command should be 16-17.

Proxies

- No log message displays in Firebox System Manager Traffic Monitor when the SMTP proxy processes an email with UTF-8 encoding in the message body. [70927]
- The Policy Manager and Web UI do not provide any warning that the WebBlocker Override may not work for HTTPS. [67208]
- HTTPS DPI (Deep Packet Inspection) does not work for users who use IE 9.0 with TLS 1.1 and 1.2 enabled, but TLS 1.0 and SSL 3.0 not enabled. [65707]

Workaround

Use a different browser, or enable TLS 1.0 and SSL 3.0 in your IE 9.0 configuration.

- The XTM device can store only one HTTPS Proxy Server certificate and can protect only one HTTPS web site at a time. [41131]
- When an XTM device is under high load, some proxy connections may not terminate correctly. [61925, 62503]
- The ability to use an HTTP caching proxy server is not available in conjunction with the TCP-UDP Proxy. [44260]
- You cannot make a SIP-based call from Polycom PVX softphone behind a Firebox to a Polycom PVX on the external network. [38567]

Workaround

You can use the H.323 protocol instead of SIP.

 When you try to stream YouTube videos from an Apple device running iOS, you may see this error message: "The server is not correctly configured."

Workaround

- 1. Edit your HTTP proxy policy.
- 2. Click View/Edit proxy.
- 3. Select the Allow range requests through unmodified check box.
- 4. Save this change to your XTM device.
- The SIP-ALG does not send the Contact header correctly when the Contact header contains a domain name. It only sends an empty string of: Contact: <>. If the Contact header contains an IP address, the SIP-ALG sends the Contact header correctly: Contact: <sip:10.1.1.2:5060>. [59622]

Workaround

Configure the PBX to send the Contact header with an IP address, not a domain name.

Security Subscriptions

- If you change the DNS configuration on your XTM device, you must restart the XTM device or re-save your configuration to your XTM device for spamBlocker to work correctly. [71532]
- The Trusted Email Forwarders feature does not work when you use spamBlocker with Mailshell. [71489]
- Some IPS signature information, such as the CVE number, is not available in Firebox System Manager.
 We provide search capabilities and CVE information for IPS signatures on a web security portal for IPS on the WatchGuard web site, which you can access at http://www.watchguard.com/SecurityPortal/ThreatDB.aspx
- Skype detection blocks only new Skype sessions. If a user is already logged in to Skype and a Skype session is already started when Application Control is enabled, Application Control may not detect the activity.
- For XTM 2 Series devices only, Application Control is temporarily disabled during an upgrade, back up, or restore. When the operation is complete, Application Control starts to work again.
- It is not possible to assign a role for Application Control management from the WatchGuard System Manager role-based administration feature. [59204]
- You cannot use a WebBlocker Server through a branch office VPN tunnel. [56319]

Networking

- If you manually created dynamic routing policies in Fireware XTM v11.5.x or earlier, the To and From
 lists in these policies are cleared when you upgrade to v11.6. If dynamic routing is enabled, new policies
 will be created automatically when you upgrade. [67721]
- Policy Checker does not work when your XTM device is configured in Bridge mode. [66855]
- An apostrophe in a DHCP reservation name causes the DHCP reservation to fail. [65529]
- You cannot configure traffic management actions or use QoS marking on VLANs. [56971, 42093]
- You cannot bridge a wireless interface to a VLAN interface. [41977]
- The Web Setup Wizard can fail if your computer is directly connected to an XTM 2 Series device as a DHCP client when you start the Web Setup Wizard. This can occur because the computer cannot get an IP address quickly enough after the device reboots during the wizard. [42550]

Workaround

- 1. If your computer is directly connected to the XTM 2 Series device during the Web Setup Wizard, use a static IP address on your computer.
- 2. Use a switch or hub between your computer and the XTM 2 Series device when you run the Web Setup Wizard.
- When a secondary network is configured for an XTM 2 Series device configured in Drop-In Mode, it can sometimes take a few minutes for computers that connect to the secondary network to appear in the ARP list of the XTM 2 Series. [42731]
- You must make sure that any disabled network interfaces do not have the same IP address as any
 active network interface or routing problems can occur. [37807]
- If you enable the MAC/IP binding with the Only allow traffic sent from or to these MAC/IP addresses
 check box, but do not add any entries to the table, the MAC/IP binding feature does not become active.
 This is to help make sure administrators do not accidentally block themselves from their own XTM
 device. [36934]
- Any network interfaces that are part of a bridge configuration disconnect and re-connect automatically
 when you save a configuration from a computer on the bridge network that includes configuration
 changes to a network interface. [39474]

- When you change the IP address of a VLAN configured on an external interface from static to PPPoE and the Firebox cannot get a PPPoE address, Firebox System Manager and the Web UI may continue to show the previously used static IP address. [39374]
- When you configure your XTM device with a Mixed Routing Mode configuration, any bridged interfaces show their interface and default gateway IP address as 0.0.0.0 in the Web UI. [39389]
- When you configure your XTM device in Bridge Mode, the LCD display on your XTM device shows the IP address of the bridged interfaces as 0.0.0.0. /393241
- When you configure your XTM device in Bridge Mode, the HTTP redirect feature is configurable from the user interface but does not work in this release. [38870]
- Static MAC/IP address binding does not work when your XTM device is configured in Bridge mode.
 /36900
- When you change your configuration mode from Mixed Routing to Bridge or from Bridge to Mixed Routing, the CLI and Web UI may continue to show the previous configuration mode. [38896]
- The dynamic routing of RIPv1 does not work. [40880]
- When an IP address is added to the Temporary Blocked Site list by the administrator through the Firebox System Manager > Blocked Sites tab, the expiration time is constantly reset when traffic is received from the IP address. [42089]

Multi-WAN

- The multi-WAN sticky connection does not work if your device is configured to use the multi-WAN Routing Table mode. [62950]
- When you enable the multi-WAN Immediate Failback option for WAN failover, some traffic may fail over gradually. [42363]

Wireless

The 5GHz Wireless band does not work when you use channels 36, 40, 149 or 165. [65559]

Authentication

Citrix 4.5/5/0 servers installed in VMware do not work with Terminal Server Single Sign-On. [66156]

Workaround

This feature works with Citrix 6.0 and 6.5 servers installed in VMware.

- Clientless SSO is not supported on a TLS-Enabled Active Directory environment.
- If you use Terminal Services authentication, no authentication verification is done against traffic of any
 protocol that is not TCP or UDP. This includes DNS, NetBIOS, and ICMP traffic.
- It is not possible to use the *Automatically redirect users to the authentication page* authentication option together with Terminal Services authentication.
- To enable your XTM device to correctly process system-related traffic from your Terminal or Citrix server, the Terminal Services Agent uses a special user account named Backend-Service. Because of this, you may need to add policies to allow traffic from this user account through your XTM device. You can learn more about how Backend-Service operates in the product help system.
- For the Authentication Redirect feature to operate correctly, HTTP or HTTPS traffic cannot be allowed through an outgoing policy based on IP addresses or aliases that contain IP addresses. The Authentication Redirect feature operates only when policies for port 80 and 443 are configured for user or user group authentication. [37241]

Centralized Management

- You cannot create a new user account for role-based administration from the Management Server that
 includes unsupported special characters, such as an underscore. You must create the user account
 from WatchGuard Server Center. [70464]
- There is no option to set up a Traffic Management action in an XTM v11.x Device Configuration Template. [55732]
- If you used Centralized Management with devices subscribed to templates in earlier versions of WSM, when you upgrade from WSM 11.x to v11.4 or higher, these templates are updated and the devices are no longer subscribed. Each device retains its template configuration. Existing templates are updated to use "T_" in their object names (to match the object names in the devices that used to subscribe to them). After you upgrade, you'll see the template upgrade that occurs during upgrade in your revision history.
- When a XTM template is applied to a managed device, the Management Server creates a new
 configuration revision for the device only if the new revision is going to be different from the current
 revision. There is also no feedback about why a new configuration revision was not created. [57934]

Logging and Reporting

 When you change the log level for your WatchGuard Log Server and click Apply, the change does not take effect. [60088]

Workaround

- 1. In WatchGuard Server Center, on the Log Server Logging tab, change the log level for log messages from the Log Server and click **Apply**.
- 2. In the Servers tree, right-click Log Server and select **Stop Server**. In the confirmation message, select **Yes**.
- 3. Right-click Log Server again and select Start Server.
- The Denied Packets Summary report is not yet available in the Log and Report Manager. [63192]
- The PDF output of the Web Activity Trend report does not include time labels on the x-axis when viewed in Log and Report Manager. Date and time information is included in the table below the report. [64162]
- When you upgrade from Fireware XTM v11.4.x to v11.5.1, reports generated near the time of the upgrade may not show up in Log and Report Manager. [64325]
- If a daily report schedule name includes a colon or certain other characters (for example: "1:35"), the system returns an error. [63427]

Workaround

Make sure that your report schedule names use only characters that are valid in Windows file names. You can find valid characters in articles such as http://msdn.microsoft.com/en-us/library/windows/desktop/aa365247%28v=vs.85%29.aspx.

- Log collector will crash when it reaches the 2GB virtual size limit on 32-bit Windows systems. [64249]
- There are two sorting issues in the new Log and Report Manager. When you sort by Destination, the
 field sorts by IP address and not the destination host name (if available). When you sort by Disposition,
 some items in the "deny" state do not sort accurately within groups. [62879]
- Any configured daily or weekly "Archived Reports" you have in your v11.3 configuration are automatically converted to scheduled reports after you upgrade to WSM v11.4 or higher.

Mobile VPN

- You cannot generate a Mobile VPN with IPSec configuration file when the group name contains the characters the asterisk or period characters(*, .). [66815]
- If you set the diagnostic log level for Mobile VPN with SSL traffic to "debug" level, log messages stop displaying in Firebox System Manager > Traffic Manager. [65165]

Workaround

Set the diagnostic log level for Mobile VPN with SSL to any log level less granular than "debug".

- If you add a new feature key that adds Mobile VPN with SSL licenses for your XTM device, you must reboot your XTM device to enable the additional Mobile VPN with SSL users. [65620]
- When you connect a Mobile VPN wth SSL v11.5.1 client for the first time to an XTM device upgraded to v11.5.2, the client upgrade sometimes fails. [65635]

Workaround

Install the Mobile VPN with SSL client manually.

- You cannot establish a Mobile VPN with SSL connection from a Windows-based computer when the Windows system account is Chinese. [58208]
- When you use the built in IPSec client from an iPhone or iPad, the client connection will disconnect
 when the connection duration reaches 1 hour and 45 minutes. This is caused by a limitation in the Cisco
 client used by iPhone/iPad. You must reconnect the IPSec client to reestablish the VPN tunnel. [63147]
- Mobile VPN with PPTP connections from Android mobile devices do not work consistently on 3G mobile networks. [63451]
- Connections from the Mobile VPN with IPSec client can route through the wrong external interface when the XTM device is configured for multi-WAN in round-robin mode. [64386]
- You cannot configure Mobile VPN with SSL to bridge network traffic to a bridged interface. [61844]
- Mobile VPN with SSL users cannot connect to some network resources through a branch office VPN tunnel that terminates on an active/active FireCluster. [61549]
- You cannot ping the IP address of the XTM device interface to which a Shrew Soft VPN client established a VPN tunnel. You can ping computers on that network, but not the interface IP address itself. [60988]
- Shrew Soft VPN client connections can drop if there are multiple cilents connected to an XTM device at the same time issuing Phase 2 rekeys. [60261]
- Phase 1 rekeys initiated by the Shrew Soft VPN client cause the client to be disconnected, if connected more than 24 hours. In this case, we recommend that you set the rekey on your XTM device to 23 hours one hour shorter than the rekey hard-coded in the Shrew Soft client configuration. This forces the XTM device to initiate the rekey, and gives the client a notification that the tunnel must be re-established. [60260, 60259]
- A continuous FTP session over a Mobile VPN with IPSec connection could get terminated if an IPSec rekey occurs during the FTP transfer. [32769]

Workaround

Increase the rekey byte count.

• The Mobile VPN for SSL Mac client may not be able to connect to an XTM device when the authentication algorithm is set to SHA 256. [35724]

Branch Office VPN

- Manual branch office VPN fails when the pre-shared key exceeds 50 characters. [65215]
- Do not use the same name for both a VPN Gateway and a VPN Tunnel. [66412]
- When you configure your XTM device in multi-WAN mode, you must select which interfaces to include
 in your multi-WAN configuration. If there are any interfaces that you choose not to include in your multiWAN configuration (i.e. you clear the check box for that interface), the system does not create a route
 for that network. This can cause a problem if you have a branch office VPN configured to include that
 same interface. In this case, the VPN tunnel can fail to negotiate with its remote peer. [57153]

Workaround

If you use multi-WAN and have problems with your branch office VPN tunnels failing to negotiate with their remote peers, you must open your multi-WAN configuration and select Configure adjacent to your chosen multi-WAN configuration mode. Make sure that the appropriate interfaces are included in your multi-WAN configuration.

- A branch office VPN tunnel does not pass traffic if an inbound static NAT policy that includes IP 50 and IP 51 protocols exists for the external IP address of the XTM device. [41822]
- Managed branch office VPN tunnels cannot be established if the CRL distribution point (for example, the WatchGuard Management Server or a third-party CRL distribution site you use) is offline. [55946]
- The use of Any in a BOVPN tunnel route is changed in Fireware XTM. If a branch office VPN tunnel
 uses Any for the Local part of a tunnel route, Fireware XTM interprets this to mean network 0.0.0.0 and
 subnet mask 0.0.0.0 (in slash notation, 0.0.0.0/0). If the remote IPSec peer does not send 0.0.0.0/0 as
 its Phase 2 ID, Phase 2 negotiations fail. [40098]

Workaround

Do not use *Any* for the Local or the Remote part of the tunnel route. Change the Local part of your tunnel route. Type the IP addresses of computers behind the XTM device that actually participate in the tunnel routing. Contact the administrator of the remote IPSec peer to determine what that device uses for the Remote part of its tunnel route (or the Remote part of its Phase 2 ID).

• If you have a large number of branch office VPN tunnels in your configuration, the tunnels may take a long time to appear in Policy Manager. [35919]

Workaround

From Policy Manager, select **View > Policy Highlighting**. Clear the **Highlight Firewall policies based on traffic type** check box.

Using the CLI

The Fireware XTM CLI (Command Line Interface) is fully supported for v11.x releases. For information on how to start and use the CLI, see the *CLI Command Reference Guide*. You can download the latest CLI guide from the documentation web site at http://www.watchguard.com/help/documentation/xtm.asp.

Technical Assistance

For technical assistance, contact WatchGuard Technical Support by telephone or log in to the WatchGuard Portal on the Web at http://www.watchguard.com/support. When you contact Technical Support, you must supply your registered Product Serial Number or Partner ID.

	Phone Number
U.S. End Users	877.232.3531
International End Users	+1 206.613.0456
Authorized WatchGuard Resellers	206.521.8375