

## Fireware XTM v11.6.5 CSP1

### Supported Devices

XTM 2, 3, 5, 8, 800, 1500, and 2500 Series  
XTM 1050, XTM 2050, XTMv

Appliance Build # 419019

WSM v11.7 or higher is needed to manage a Firebox running Fireware XTM 11.6.5 CSP. 11.6.5 CSP releases are cumulative and include all fixes in 11.6.5 Update 1.

Software Available at:

[ftp.watchguard.com/11.6.5\\_CSP/CSP1/](ftp.watchguard.com/11.6.5_CSP/CSP1/)

Username: XTM\_CSP

Password: S0NofTr1ton

### Resolved Issues:

#### CSP1 (Build # 419019)

This release contains further improvements to efficacy of spamBlocker with Mailshell

[BUG71300] Resolved a Kernel crash which occurred when using FireCluster under high traffic conditions

[BUG71738] Resolved Memory leak when an external interface is configured for DHCP and the DHCP server is not responding

[BUG71589] Resolved issue causing the firewalld process to crash.

[BUG67075] SNMP "Get" now displays the accurate number of Branch Office VPN tunnels.

[BUG70202, BUG71732, BUG70342]: Resolved issue causing Branch Office VPN traffic to stop passing when using Firebox models XTM 330, XTM 3, XTM 25/26.

[BUG70491] The widsd process no longer uses excess CPU

[BUG71926] Fixed issue causing the loggerd process to use excessive CPU.

[BUG71871] Improved the HTTP Proxy MSS handling to allow for MTU to be adjusted independently for the in and out proxy channels. This improvement will prevent applications like Facebook from stalling.

[BUG69331] Interface link down/up behavior has been improved for XTM 21-23, XTM 25/56 and XTM 33.

[RFE71314] The Firebox serial number will now display in the HTTP proxy deny message.

[BUG70955] Resolved issue causing the SSID for guest network to stop broadcasting.

[BUG69132] Resolved issue causing the Wireless Guest interface status to show as down but the interface continues to function.

[BUG70318] When using wireless the log line “ath: phy0: failed to stop TX DMA, queue=0x005!” no longer occurs.

[BUG72586] The hostapd debug logs no longer appear when diagnostic logging is disabled.

[BUG68975, RFE64455] The Firebox DHCP server now properly sends a NACK reply for devices with an existing DHCP lease.

[BUG71323] Resolved issue which caused Branch Office VPN IPSec VPN to stop functioning after upgrade from 11.4.x to 11.6.x or 11.7.x.

[BUG69493, BUG65892] Resolved issue which caused the Intel Network Interface Cards to hang and stop passing traffic for short periods of time on XTM 5-series and above.

[BUG72048] Resolved Cross site scripting vulnerability on the SSLVPN authentication port related to an invalid login redirect.

### Description of v11.6.5 CSP files available for download:

XTM\_OS\_XTM800\_1500\_2500\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 800, 1500,2500 Series Firewalls using policy manager or the WebUI

XTM\_OS\_2050\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the 2050 using policy manager or the WebUI

XTM\_OS\_1050\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the 1050 using policy manager or the WebUI

XTM\_OS\_XTM8\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 8-series using policy manager or the WebUI

XTM\_OS\_XTM5\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 5-series using policy manager or the WebUI

XTM\_OS\_XTM330\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 330 using policy manager or the WebUI

XTM\_OS\_XTM3\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 33 using policy manager or the WebUI

XTM\_OS\_XTM2\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 2-series using policy manager or the WebUI

XTM\_OS\_XTM2A6\_11\_6\_5\_CSP.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM25 and XTM26 using policy manager or the WebUI

XTMv\_11\_6\_5.ova -- file to do initial installation of XTMv

XTM\_OS\_XTMV\_11\_6\_5\_CSP.exe -- file to upgrade an existing XTMv installation