Fireware XTM v11.9.1 CSP 1 Release Notes

Supported Devices	Firebox T10, XTM 25/26 XTM 3, 5, 8, 800, 1500, and 2500 Series XTM 1050, XTM 2050, XTMv, WatchGuard AP
Fireware XTM OS Build	453357
WatchGuard System Manager Build	N/A
Revision Date	July 15, 2014

Software Available for Download

To download software for this CSP release, go to:

ftp.watchguard.com/11.9.1_CSP/CSP1/
Username: XTM_CSP
Password: S0NofTr1ton

WatchGuard System Manager v11.9.1 or higher is needed to manage a device running Fireware XTM v11.9.1 CSP 1. Fireware XTM OS v11.9.1 CSP releases are cumulative. A description of available software files is included below the *Resolved Issues* section.

Resolved Issues in CSP 1 (Build 453357)

- [BUG81527] Resolved issue which prevented the Firebox from obtaining an external IP, via DHCP, if the Gateway was on a different subnet then the assigned external IP.
- [BUG81399, BUG81400] This release fixes several crashes which occurred when running the XTM appliance in Bridge Mode.
- [BUG81544] This release resolves an issue which caused the scanning process for Gateway AV to fail.
- [BUG81244] Fixed memory leak in the Gateway AV scanning process.
- [BUG81491] The WebUI no longer has PFS enabled by default for Branch Office VPN
- [BUG81351] The Security Services reporting logs are improved to allow for time slice reports.
- [BUG81158] Resolved issue which prevented ECMP from working properly with two Virtual Interface Branch Office VPN tunnels.

- [BUG75254] Resolved issue which caused XTM wireless to fail with logs showing: *ath: phy0: Failed to stop TX DMA*

- [BUG77716] Resolved issue which caused XTM wireless connection to fail when Rogue AP detection is enabled.

- [BUG81353] Resolved a memory corruption issue which prevented the capture of Proxy crash logs.

- [BUG80943, BUG81361] This release resolves an issue which caused High CPU utilization from the snmpd process.

- [BUG80992,BUG80936] The WebUI will now properly display Static Nat entries in the policy list.

- [BUG80783] Using Outgoing Interface Bandwidth on the Trusted Interface no longer significantly reduces download speed.

- [BUG81006] Fixed issue which caused traffic to not pass through the proxy policies on a central site when traffic was generated from the remote site through a Branch Office VPN tunnels using 1 to 1 NAT and Zero Route.

- [BUG77129] Resolved issue with path MTU which prevented traffic from successfully passing through a zero route Branch Office VPN.

- [BUG71223] Reduced the delay in web site loading when WebBlocker server is unavailable and access to the website is allowed.

- [BUG81153] WebBlocker now properly handles invalid WebBlocker requests.

Available Files in this CSP Release

Software File	For Device Model	Information
XTM_OS_XTM800_1500_2500_11_9_1.exe	XTM 800, 1500, or 2500 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM2050_11_9_1.exe	XTM 2050 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM1050_11_9_1.exe	XTM 1050 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM8_11_9_1.exe	XTM 8 Series devices	Appliance software to install

		sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM5_11_9_1.exe	XTM 5 Series devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM330_11_9_1.exe	XTM 330 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM33_11_9_1.exe	XTM 33 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM2A6_11_9_1.exe	XTM 25 & 26 devices (including wireless)	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_T10_11_9_1.exe	Firebox T10 devices	Appliance software to install sysa-dl file on your computer to upload to your Firebox using Policy Manager or the XTM Web UI
XTMv_11_9_1.ova	XTMv with VMware	File to do initial installation of XTMv for VMware
xtmv_11_9_1_vhd.zip	XTMv with Hyper-V	File to do initial installation of XTMv for Hyper-V
XTM_OS_XTMV_11_9_1.exe	XTMv, all editions	File to upgrade an existing XTMv installation. Applies to VMware and Hyper-V installations.