Fireware v12.0.1 CSP 2 Release Notes

Supported Devices	Firebox T10, T15, T30, T35, T50, T55, T70, M200, M300, M370, M400, M440 M470, M500, M570, M670, M4600, M5600 XTM 3, 8, 800, 1500, and 2500 Series XTM 25, XTM 26, XTM 515, XTM 525, XTM 535, XTM 545, XTM 1050, XTM 2050 FireboxV, XTMv, Firebox Cloud, WatchGuard AP
Fireware OS Build	546744
WatchGuard System Manager Build	N/A
Revision Date	16 November 2017

Software Available for Download

To download software for this CSP release, go to: 12_0_1_CSP2

WatchGuard System Manager v12.0.1 or higher is needed to manage a device running a Fireware v12.0.1 CSP build. There is no WSM update available with this CSP. Fireware v12.0.1 CSP releases are cumulative. A description of available software files is included below the *Resolved Issues* section.

Note: Because this is CSP software and not a generally available release, the Fireware Web UI > Upgrade OS page will display the message "This device is on an unreleased version of the OS".   The .exe installers are not digitally signed.

Resolved Issues in Fireware 12.0.1 CSP 2 (Build 546744)

- This release resolves an issue introduced with 12.0.1 CSP 1 which caused some websites to not load properly through an HTTP proxy when using Microsoft Internet Explorer 11 or Edge browser. *[FBX-8995]*
- This release resolves a proxy process crash when changing proxy actions associated with a proxy policy. *[FBX-8900]*
- This release resolves a memory leak associated with HTTP proxy gzip file scanning. *[FBX-9079]*

Resolved Issues in Fireware 12.0.1 CSP 1 (Build 546589)

- This release resolves an issue that prevented Network Interfaces from passing traffic after a reboot on Firebox M200/M300 appliances using Fireware v12.0.1 Build 545166. *[FBX-8865]*
- This release resolves an issue in previous 12.x releases that prevented certificates from being restored in a backup image. *[FBX-8705]*
- This release resolves an issue that prevented certificates from correctly synchronizing between FireCluster members. *[FBX-7547]*
- A FireCluster process crash has been resolved. *[FBX-8283]*
- The Firebox now correctly sends a new DNS query for configured FDQNs when its TTL has expired and no DNS request was detected passing through the Firebox. *[FBX-2531]*
- Users should no longer see encoding errors downloading gzip encoded files and all page elements should fully render correctly when using the HTTP proxy with Gateway AV Scan errors set to **Allow**. *[FBX-8066]*
- This release resolves an issue that prevented an HTTP POST request from completing though an HTTP Proxy with Gateway AV enabled. *[FBX-8742]*
- This release resolves a small memory leak when using APT Blocker. *[FBX-9034]*
- This release resolves several Proxy process crashes. *[FBX-8896, FBX-8925, FBX-8899]*

Available Files in this CSP Release

If you have…	Select from these Fireware OS packages
Firebox M5600	`Firebox_OS_M4600_M5600_12_0_1.exe` `firebox_M4600_M5600_12_0_1.zip`
Firebox M4600	`Firebox_OS_M4600_M5600_12_0_1.exe` `firebox_M4600_M5600_12_0_1.zip`
Firebox M670	`Firebox_OS_M370_M470_M570_M670_12_0_1.exe` `firebox_M370_M470_M570_M670_12_0_1.zip`
Firebox M570	`Firebox_OS_M370_M470_M570_M670_12_0_1.exe` `firebox_M370_M470_M570_M670_12_0_1.zip`
Firebox M500	`Firebox_OS_M400_M500_12_0_1.exe` `firebox_M400_M500_12_0_1.zip`

If you have…	Select from these Fireware OS packages
Firebox M470	`Firebox_OS_M370_M470_M570_M670_12_0_1.exe` `firebox_M370_M470_M570_M670_12_0_1.zip`
Firebox M440	`Firebox_OS_M440_12_0_1.exe` `firebox_M440_12_0_1.zip`
Firebox M400	`Firebox_OS_M400_M500_12_0_1.exe` `firebox_M400_M500_12_0_1.zip`
Firebox M370	`Firebox_OS_M370_M470_M570_M670_12_0_1.exe` `firebox_M370_M470_M570_M670_12_0_1.zip`
Firebox M300	`Firebox_OS_M200_M300_12_0_1.exe` `firebox_M200_M300_12_0_1.zip`
Firebox M200	`Firebox_OS_M200_M300_12_0_1.exe` `firebox_M200_M300_12_0_1.zip`
Firebox T70	`Firebox_OS_T70_12_0_1.exe` `firebox_T70_12_0_1.zip`
Firebox T55	`Firebox_OS_T55_12_0_1.exe` `Firebox_T55_12_0_1.zip`
Firebox T50	`Firebox_OS_T30_T50_12_0_1.exe` `firebox_T30_T50_12_0_1.zip`
Firebox T35	`Firebox_OS_T35_12_0_1.exe` `Firebox_T35_12_0_1.zip`
Firebox T30	`Firebox_OS_T30_T50_12_0_1.exe` `firebox_T30_T50_12_0_1.zip`
Firebox T15	`Firebox_OS_T15_12_0_1.exe` `Firebox_T15_12_0_1.zip`
Firebox T10	`Firebox_OS_T10_12_0_1.exe` `firebox_T10_12_0_1.zip`

FireboxV
All editions for VMware
	`FireboxV_12_0_1.ova`
	`XTM_OS_FireboxV_12_0_1.exe`
	`xtm_FireboxV_12_0_1.zip`

FireboxV
All editions for Hyper-V
	`FireboxV_12_0_1_vhd.zip`
	`XTM_OS_FireboxV_12_0_1.exe`
	`xtm_FireboxV_12_0_1.zip`

If you have…	Select from these Fireware OS packages
Firebox Cloud	firebox_FireboxCloud_12_0_1.zip
XTM 2500 Series	XTM_OS_XTM800_1500_2500_12_0_1.exe xtm_xtm800_1500_2500_12_0_1.zip
XTM 2050	XTM_OS_XTM2050_12_0_1.exe xtm_xtm2050_12_0_1.zip
XTM 1500 Series	XTM_OS_XTM800_1500_2500_12_0_1.exe xtm_xtm800_1500_2500_12_0_1.zip
XTM 1050	XTM_OS_XTM1050_12_0_1.exe xtm_xtm1050_12_0_1.zip
XTM 800 Series	XTM_OS_XTM800_1500_2500_12_0_1.exe xtm_xtm800_1500_2500_12_0_1.zip
XTM 8 Series	XTM_OS_XTM8_12_0_1.exe xtm_xtm8_12_0_1.zip
XTM 5 Series, *Models 515, 525, 535, and 545 only*	XTM_OS_XTM5_12_0_1.exe xtm_xtm5_12_0_1.zip
XTM 330	XTM_OS_XTM330_12_0_1.exe xtm_xtm330_12_0_1.zip
XTM 33	XTM_OS_XTM3_12_0_1.exe xtm_xtm3_12_0_1.zip
XTM 25/26	XTM_OS_XTM2A6_12_0_1.exe xtm_xtm2a6_12_0_1.zip
XTMv All editions for VMware	xtmv_12_0_1.ova XTM_OS_xtmv_12_0_1.exe xtm_xtmv_12_0_1.zip
XTMv All editions for Hyper-V	xtmv_12_0_1_vhd.zip XTM_OS_XTMv_12_0_1.exe xtm_xtmv_12_0_1.zip