Fireware XTM v11.9.3 CSP 1 Release Notes

Supported Devices	Firebox T10, XTM 25/26, Firebox M440 XTM 3, 5, 8, 800, 1500, and 2500 Series XTM 1050, XTM 2050, XTMv, WatchGuard AP
Fireware XTM OS Build	460269, *460260 for Firebox M440, XTM 800, 1500, and 2500 Series
WatchGuard System Manager Build	N/A
Revision Date	October 30, 2014

Software Available for Download

To download software for this CSP release, go to:

ftp.watchguard.com/11.9.3_CSP/CSP1/
Username: XTM_CSP
Password: S0NofTr1ton

WatchGuard System Manager v11.9.3 or higher is needed to manage a device running Fireware XTM v11.9.3 CSP. Fireware XTM OS v11.9.3 CSP releases are cumulative. A description of available software files is included below the *Resolved Issues* section.

Resolved Issues in CSP 1 (Build 460269, *460260 for XTM 800, 1500, and 2500 Series)

- In response to the recent "Poodle" vulnerability, this release disables support for SSLv3 for HTTPS connections to the Firebox XTM Web UI. [BUG82823]
- This release resolves several proxy process crashes. [BUG81811, BUG82091,82665,82196,82131]
- The unnecessary log message "scan_wg: failed to calculate MD5 hash for file" no longer appears in the log file. [BUG82036]
- Blocked sites now correctly handle duplicate entries where a CIDR entry and an IP range are within the same subnet. [BUG75696]
- This release resolves a memory leak when using the SIP ALG. [BUG82764]
- This release resolves a memory leak that occurred when using the WebBlocker Override feature. [BUG82441,BUG82442]

- When using the Web UI, the password used for the AD/LDAP Searching User is no longer shown in clear text. [BUG82183]

- SIP invite requests are no longer dropped by the SIP-ALG when a VoIP call is put on hold. [BUG81794]

- SIP-ALG custom policies for UDP now work correctly. [BUG79592]

- You can now correctly enable and disable the individual policy diagnostic level for the TCP-UDP proxy. [BUG81846]

- When you enable per Proxy Policy diagnostic logging for HTTPS Content Inspection, diagnostic logging for all HTTPS proxy policies with Content Inspection is no longer enabled. [BUG82374]

- This release reduces the occurrence of the unnecessary log message "xt_wgaccount: wgact_get: Invalid policy ID XXX requested". [BUG74936]

- This release resolves an issue that prevented Traffic Monitor from displaying some DNS proxy log messages. [BUG82290]

- This release resolves an issue that caused the scand process used for Gateway AV to crash and restart. [BUG82047,BUG82770]

- The SMTP proxy now correctly logs the recipient email addresses when multiple emails are sent through the same SMTP connection. [BUG82359]

- Secondary IP addresses now respond correctly to ARP request when your Firebox or XTM device is configured in drop-in mode. [BUG78329]

Available Files in this CSP Release

Software File	For Device Model	Information
XTM_OS_XTM800_1500_2500_11_9_3.exe	XTM 800, 1500, or 2500 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM2050_11_9_3.exe	XTM 2050 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM1050_11_9_3.exe	XTM 1050 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM8_11_9_3.exe	XTM 8 Series devices	Appliance software to install

		sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM5_11_9_3.exe	XTM 5 Series devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_M440_11_9_3.exe	M440 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM330_11_9_3.exe	XTM 330 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM33_11_9_3.exe	XTM 33 devices	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_XTM2A6_11_9_3.exe	XTM 25 & 26 devices (including wireless)	Appliance software to install sysa-dl file on your computer to upload to your XTM device using Policy Manager or the XTM Web UI
XTM_OS_T10_11_9_3.exe	Firebox T10 devices	Appliance software to install sysa-dl file on your computer to upload to your Firebox using Policy Manager or the XTM Web UI
XTMv_11_9_3.ova	XTMv with VMware	File to do initial installation of XTMv for VMware
xtmv_11_9_3_vhd.zip	XTMv with Hyper-V	File to do initial installation of XTMv for Hyper-V
XTM_OS_XTMV_11_9_3.exe	XTMv, all editions	File to upgrade an existing XTMv installation. Applies to VMware and Hyper-V installations.