Fireware XTM v11.7.4 CSP4

Supported Devices

XTM 3, 5, 8, 800, 1500, and 2500 Series
XTM 25, XTM 26, XTM 1050, XTM 2050
XTMv, WatchGuard AP

Fireware XTM OS Build # 434038

WSM v11.7.4 or higher is needed to manage a Firebox running Fireware XTM 11.7.4 CSP.   11.7.4 CSP releases are cumulative.

Software Available at:

ftp.watchguard.com/11.7.4_CSP/CSP4/

Username: XTM_CSP

Password: S0NofTr1ton

Resolved Issues:

CSP1 (Build # 432146)

[BUG72763] Missing log in Event log and entry in HAopevent for LA link down on Master

[BUG76463] A/A cluster unable to load balance after cluster formation

[BUG70927] When email body include UTF-8 encoding, then FSM can't display the log

[BUG74595] WebBlocker enabled (both types) causing traffic to fail through HTTP/HTTPS Proxy

[BUG74753] WebBlocker: add RTT measurement for websense cloud server

[RFE74313] Increased nf_conntrack_expect_max limit to allow for high dynamic channel setup rate.

[BUG75131] Resolved issue causing the iked process to crash.

[BUG73746, BUG73246] DHCP Relay not working using vlans

[BUG72916, BUG72904] interface stuck in "down" state after cluster failover

[BUG74628] Resolved kernel memory leak on backup member in nf_conntrack

[BUG73159] Fully Managed cluster XTM - With template saves causes config.hash values to become mismatched

[BUG72904] Link monitor by domain name causes external interface state down on new master

[BUG75868] HTTP/SMTP AV scanning error="no text for this error code"

CSP2 (Build # 432459)

[BUG76979] spamBlocker not working on XTM1520-RP

CSP3 (Build # 433350)

[BUG76752] Buffer overflow claimed in WGagent

[BUG73394] wgrelayd died unexpectedly on signal 6

[BUG73506] IPSec SP is not downloaded to kernel after IPSec SA created.

CSP4 (Build # 434038)

[BUG77122] The HTTP proxy with Websense stops passing traffic for several minutes after multi WAN failover occurs.

Description of v11.7.4 CSP files available for download:

XTM_OS_XTM800_1500_2500_11_7_4.exe -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 800, 1500,2500 Series Firewalls using policy manager or the WebUI

XTM_OS_XTM2050_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the 2050 using policy manager or the WebUI

XTM_OS_XTM1050_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the 1050 using policy manager or the WebUI

XTM_OS_XTM8_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 8-series using policy manager or the WebUI

XTM_OS_XTM5_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 5-series using policy manager or the WebUI

XTM_OS_XTM330_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 330 using policy manager or the WebUI

XTM_OS_XTM330_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the XTM 33 using policy manager or the WebUI

XTM_OS_XTM2A6_11_7_4.exe   -- appliance firmware to install sysa-dl file on your PC to upload to the XTM25 and XTM26 using policy manager or the WebUI

XTMv_11_7_4.ova -- file to do initial installation of XTMv

XTM_OS_XTMV_11_7_4.exe -- file to upgrade an existing XTMv installation. Applies to VMware and Hyper-V installations